

JAMES E. RISCH -- Governor RICHARD M. ARMSTRONG -- Director DEBBY RANSOM, R.N., R.H.I.T — Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

November 2, 2006

Amanda Olsen, Administrator Aspen Grove Assisted Living - Gooding 745 California Ave Gooding, ID 83330

License #: RC-493

Dear Ms. Olsen:

On September 5, 2006, a life safety code survey was conducted at Aspen Grove Assisted Living - Gooding. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Chris Laumann, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

Team Leader

Health Facility Surveyor

Facility Fire, Life Safety, and Construction Program

CL/slc

c:

Mark Grimes, Supervisor, Facility Fire, Life Safety, and Construction Program



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.f.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, idaho 83720-033 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

September 13, 2006

Denise Dye Donnell, Administrator Aspen Grove Assisted Living - Gooding 745 California Ave Gooding, ID 83330

FILE COPY

Dear Ms. Donnell:

On September 5, 2006, a life safety code survey was conducted at Aspen Grove Assisted Living - Gooding. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by October 5, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - ENTIRE BUILDING	(X3) DATE SURVEY
AND PLAN OF CORRECTION	IDENTIFICATION NUMBER:		COMPLETED
	13R493	B. WING	09/05/2006

STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 745 CALIFORNIA AVE **ASPEN GROVE ASSISTED LIVING - GOODING** GOODING, ID 83330 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE DATE (X4) ID (EACH DEFICIENCY MUST BE PRECEEDED BY FULL PRÉFIX PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) R9999 **Initial Comments** R9999 The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on Sept 5, 2006. The surveyors conducting the survey was: Eric Mundell Team Leader Health Facility Surveyor Chris Laumann Life/Safety Surveyor

Bureau of Facility Standards

TITLE

(X6) DATE

PRATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues **Punch List**

Facility Name	Physical Address			
Aspen Grave Assisted Living.		Phone Number		
TSpen Grace Assisted Living.	745 California Ave	208) 934-5506		
Amanda Olsen 539-2006	Gooding	83330		
Survey Team Leader	Survey Type	Survey Date		
Eric Mundell	Fire Life Safety	5 Sept 2006		
NON-CORE ISSUES		15 SHF 2000		
ITEM RULE#	DESCRIPTION	BATIE		
		RESOLVED		
1 (10)102, 103:03 [mainsenance! 17	tuntor temperature was received	1 132.6° 9 5 100 0		
on work to the	41mum 12 1200F.			
2 16.03.72.450/16 An extension	cord was in use in Steeping 4.	en #3. If a 15 10 0		
	orge protector.	100		
3 16.03.77. 405.03 Medual Graves	: Trans-filling a occurring in	the garage black do		
The room was	word for other purposes as well in the	and not		
Soldy for Trus	chillis. The room ded not he	60 (1)		
caramic file/ ce	ment flow frieshed surface and	/ M		
ana was not	Sprinklered and mechanically L	untiletal.		
	ting: There was no documental	ion to 9/28/00 cd		
Chan By trum	are had been in Ada al	18 18 18		
5 16.03.22.750.05a Five Alarm Ser				
main tained on f	you the current inspection a	as not		
majn jajn ca un j	· ·			
	Rr.			
Response Required Date Signature of Facility Representative	. E C	E/VED		
October 5, 2006	OCT 1	ED		
	FACILITY STA,	1 2006		
DEC 494	STA	VDADA		
BFS-686		aina		